




TRACKER HARDWARE INSIDE

Contents	Specifications	Tools Required
(1) Tracker hardware	Max current draw: 20 mA	1/2 ["] and/or 9/16 ["] wrench
Zip ties	Operating voltage range: 12-48 VDC full battery	Dielectric Grease
(1) Instruction sheet	Operating temperature: 0-180° F	Zip Ties


For a detailed installation video and more information, go to www.flow-rite.com/battery-steward


INSTALLATION INSTRUCTIONS: Tracker Hardware





Step 1: Remove the positive cable from the battery connector. Place the current sensor over the cable with the arrow pointing towards the battery.






Step 2: Slide the sensor all the way down to the battery post and re-insert the battery cable into the connector.



Step 5: Anchor the half voltage lead (brown wire) to an inter-cell connector halfway between the positive and negative posts. Coat all anchored hardware with supplied no-ox grease.



Step 3: Secure the tracker to an inter-cell connector with a supplied zip-tie.



Step 6: Secure any loose wires with zip-ties.



Step 4: Using the supplied self tapping screws, anchor the positive lead (red wire) to the positive battery post and the negative lead (black wire) to the negative post.

www.flow-rite.com/battery-steward

960 74th St. Byron Center, MI 49315



