Flow Indicator Assembly Instructions



BA-FLW-60 only: Wrap threads 3 times with a 6" length of .5" PTFE (Teflon style) tape prior to threading into flow indicator. Tape should be wrapped in a clockwise direction and should not overlap or cover the inlet of the coupler. Coupler should be hand tightened only.





Flow Indicator Assembly Instructions



BA-FLW-60 only: Wrap threads 3 times with a 6" length of .5" PTFE (Teflon style) tape prior to threading into flow indicator. Tape should be wrapped in a clockwise direction and should not overlap or cover the inlet of the coupler. Coupler should be hand tightened only.





BL-357-021522